- Infrastructure Design
- Structural Engineering
- Planning Services
- Professional Advice
- Geotechnical & Environmental
- Surveying



DESK STUDY SITE REVIEW FOR PROPOSED 3G FOOTBALL TURF PITCH (FTP) FEASIBILITY: Laurel Park, Lower Earley, Earley, Reading RG6 3DZ

The following is based on review of readily available records to inform a 3G FTP feasibility assessment and potential constraints associated with the ground. This review does not constitute a full risk assessment and should be confirmed and supported by ground investigations where appropriate.

Item

Site overview

structures

and topography

including existing

Comments

The site comprises an existing grassed playing fields within Laurel Park with associated pavilion building and car park in the

Laurel Park with associated pavilion building and car park in the west of the site. The site located within an area surrounded by mature trees/woodland, which are present around the perimeter of the grassed field. The pitch is centred at an approximate grid reference of 475212, 171019.

Ordnance Survey mapping indicates topography of the site falls to the north east with a 60m AOD contour just off site to the south west and a 50m AOD contour toward the north eastern corner of the field.

The areas to the north, north east and west are comprised of mature deciduous trees called Moor Copse associated with Erlegh Local Nature Reserve with a stream running through this area and a lake to the west. Directly to the south of the site is Laurel Park Recreation Ground. It is comprised a grassed playing field with goalposts and pitch outlines. Residential dwellings are present to the south east and south west of the site.

Maiden Erlegh Park Recn CO Sch Sch Sch Rec Gd

Risk/Implications

Potential for some significant level changes and uneven ground across the proposed footprint and therefore some cut and fill earthworks likely to be required, subject to topographical survey. Surrounded by mature trees/woodland which is likely to impact foundations on clay soils.

JPP Geotechnical and Environmental Ltd Registered in England 11117245

Registered office

NORTHAMPTON

4 Ironstone Way Brixworth Northampton NN6 9UD T: 01604 781811 **T04-3**

Branksome Business Park Bourne Valley Road | Poole Dorset | BH12 1ED T: 01202 540888



Item Risk/Implications



Suggested proposed position of 3G AGP (extent 112m x 76m) indicated by blue outline.

Geology

There are no superficial deposits recorded across the majority of the proposed pitch, River Terrace Deposits (sand and gravel) are recorded across the eastern edge and to the immediate south of the proposed pitch extent. Superficial Boyn Hill Gravel Member (sand and gravel) deposits are present to the immediate south west of the site. The site is underlain by bedrock geology of the London Clay Formation (clay, silt and sand).

Borehole records approximately 800m to the south east of the site record silt to 0.50m bgl underlain by clayey sands and gravel to 2.30m bgl with sandy silty gravelly clays to depths of approximately 2.50m.

Near surface geology like to comprise clays and therefore be influenced by trees and low CBR with potential for desiccated near surface soils.

Hydrogeology and hydrology

The bedrock geology of the London Clay Formation is classified as unproductive strata. Superficial River Terrace Deposits and Boyn Hill Gravel Member are classified as Secondary A Aquifers. The site is not located within a Source Protection Zone with the superficial deposits present in the east of the site and to the south of the site having low groundwater vulnerability.

The nearest surface water feature to site a stream/river approximately 115m to the north of the site associated with Maiden Erlegh Lake which is present approximately 245m to the west of the site. There are no obvious drainage ditches within proximity to the site.

Nearby borehole records suggest groundwater to be present around 2.00m bgl.

Soils likely to comprise clays and no groundwater however potential for shallow groundwater within granular superficial deposits if present.

Infiltration potential

Near surface soils likely to comprise impermeable clays although potential for some granular superficial deposits in the south east which could provide some infiltration potential subject to groundwater. Evidence of herringbone land drainage from aerial images would suggest near surface ground has low permeability.

A stream is present just to the north of the site running from east to west. it leads to a lake within the Maiden Erlegh Local Nature Reserve and could provide a possible outfall.

Near surface soils likely to comprise impermeable clays. Possible superficial granular deposits in the south east. Watercourse to the north provides a potential outfall.



Item	Comments	Risk/Implications
Artificial/Made	According to the British Geological Survey, the south western	Worked ground in
Ground or landfill	area of the site is recorded as being worked ground (void),	the south western
	probably extracting River Terrace sand and gravel deposits.	area of site.
	There is a historic landfill recorded approximately 655m to the	Potential for Made
	west of the proposed pitch, a further two historical landfills are	Ground within the
	recorded approximately 800m and 960m to the south east of	extent of the
	the site. There are no authorised landfill sites mapped on site	proposed pitch.
	or in close proximity.	
Historical maps	Mapping available from 1872 shows the site to comprise an	Potential for there
	agricultural field/undeveloped rough land. To the north of the	to be Made Ground
	site are wooded areas labelled as Oldpond Copse and Moor	in the south
	Copse. Agricultural fields are present to the south, east and	western corner
	west of the site with an unnamed body of water present to the	where former
	west of the site. Historic maps from 1911 show there to be	workings/quarry is
	sewage tanks present to the north west of the site beyond	indicated however
	Oldpond Copse with a farm and associated farmland present to	it may not have
	the south of the site. The site remains largely unchanged until	been restored.
	the 1980s where a pavilion is present to the west of the site	Herringbone land
	with the fields to the south shown as Laurel Park Recreation	drainage pattern
	Ground. Historic maps appear to show a fall in levels across the	evident from aerial
	site from the south western corner to the northern corner.	images, heading towards the north
	Aerial imagery indicates that the site has remained unchanged	eastern corner.
	since the historical mapping in the 1980s until 2021, the site	
	comprises a grassed playing field with a pavilion building and	
	associated car parking to west/south west of the site. Aerial	
	images show a distinct herringbone pattern across the site	
	travelling from the building to the northern corner of the site,	
	this suggests that there is existing drainage in place.	
UXO Risk	Online mapping indicates the site to be within an area of low	No further action
	UXO risk.	required.
Coal Mining Risk	Site is not in an area of concern.	No risk identified
(or Cheshire		
Brine extraction)	LCDUD' L VICE CCEN LCON	A
Utility providers	LSBUD identifies SSEN and SGN	None shown to
records (below	Water: None crossing the site.	cross playing fields
ground and	Sewer: None crossing the site	or subject
overhead)	Electricity: Underground LV cable enters the site from the west	proposed AGP
	along the road to the pavilion building in the west of the site.	position
	None crossing playing fields.	RECORDS
	Gas: None crossing the site.	ATTACHED
Flood risk	Openreach: None crossing the site.	None identified
riooa fisk	No risk from rivers, reservoirs and seas across the site – Flood	None identified
	Zone 1. The stream to the north of the site is at risk of flooding from reservoirs.	Unlikely to require FRA.
		r na.
	Low to high risk of surface water flooding along the eastern	
	edge of the site and to the north along the stream. Areas at risk	
	of surface water flooding present adjacent to the existing	
	of surface water flooding present adjacent to the existing pavilion building.	



Item	Comments	Risk/Implications
Land and historic	No listed buildings, scheduled monuments or heritage sites	Local nature
feature	within proximity to the site.	reserve to the
designations	The site is within a SSSI Impact Risk Zone with Lodge Wood &	north of the site
	Sandiford Mill SSSI present approximately 3.2km to the north	could impact
	east of the site. Maiden Erlegh Park to the immediate north,	planning
	north east and north west of the site is designated as a local	application
	nature reserve.	

Summary of identified potential abnormalities and/or constraints

South eastern area of the site recorded as worked ground (void) and indicated by historical mapping, it may not have been restored.

Potential for cut and or fill earthworks to be required due to anticipated fall across the proposed pitch and possible uneven ground from the former worked area.

Deepening of floodlights likely to be required due to the influence of trees and dense vegetation surrounding the site and clay soils and the potential Made Ground from former workings. Piled foundations may be required.

Pitch formation could also be desiccated.

The presence of land drainage would indicate the soils exhibit low permeability.

Woodland to the north of the site is designated a Local Nature Reserve.

Potential Ground investigation scope for the proposed 3G FTP

Window sampler borehole investigation recommended due to potential deepening of foundations due to influence of trees, levelling earthworks and possible Made Ground.

Topsoil testing and analysis.

Potential for Made Ground and therefore classification of waste soils for off site disposal.

Other surveys: Topographical survey Electrical Capacity Survey

Unlikely to require FRA




Enquiry Confirmation LSBUD Ref: 23470833

Date of enquiry: 05/10/2021 Time of enquiry: 15:21

Enquirer			
Name		Phone	
Company	JPP Geotechnical & Environmental	Mobile	Not Supplied
Address	4 Ironstone Way Brixworth Northamptonshire NN6 9UD		
Email			

Enquiry Details					
Scheme/Reference	23868 Laurel Park, Earley				
Enquiry type	Initial Enquiry	Work category		Development Projects	
Start date	06/10/2021	Work type		Commercial/industrial	
End date	06/10/2021	Site size		60649 metres square	
Searched location	XY= 475212, 171019	Work type buffer*		75 metres	
Confirmed location	475215 171030				
Site Contact Name	Not Supplied		Site Phone No		Not Supplied
Description of Works	Plans obtained are used for service avoidaground investigation	ance only wh	nen brea	king grou	und during an intrusive

^{*} The WORK TYPE BUFFER is a distance added to your search area based on the Work type you have chosen.





Enquiry Confirmation LSBUD Ref: 23470833

Date of enquiry: 05/10/2021 Time of enquiry: 15:21

Asset Owners

Terms and Conditions. Please note that this enquiry is subject always to our standard terms and conditions available at www.linesearchbeforeudig.co.uk ("Terms of Use") and the disclaimer at the end of this document. Please note that in the event of any conflict or ambiguity between the terms of this Enquiry Confirmation and the Terms of Use, the Terms of Use shall take precedence.

Notes. Please ensure your contact details are correct and up to date on the system in case the LSBUD Members need to contact you.

Validity and search criteria. The results of this enquiry are based on the confirmed information you entered and are valid only as at the date of the enquiry. It is your responsibility to ensure that the Enquiry Details are correct, and LinesearchbeforeUdig accepts no responsibility for any errors or omissions in the Enquiry Details or any consequences thereof. LSBUD Members update their asset information on a regular basis so you are advised to consider this when undertaking any works. It is your responsibility to choose the period of time after which you need to resubmit any enquiry but the maximum time (after which your enquiry will no longer be dealt with by the LSBUD Helpdesk and LSBUD Members) is 28 days. If any details of the enquiry change, particularly including, but not limited to, the location of the work, then a further enquiry must be made.

Asset Owners & Responses. Please note the enquiry results include the following:

- 1. "LSBUD Members" who are asset owners who have registered their assets on the LSBUD service.
- 2. "Non LSBUD Members" are asset owners who have not registered their assets on the LSBUD service but LSBUD is aware of their existence. Please note that there could be other asset owners within your search area.

Below are three lists of asset owners:

- 1. LSBUD Members who have assets registered within your search area. ("Affected")
 - a. These LSBUD Members will either:
 - i. Ask for further information ("Email Additional Info" noted in status). The additional information includes: Site contact name and number, Location plan, Detailed plan (minimum scale 1:2500), Cross sectional drawings (if available), Work Specification.
 - ii. Respond directly to you ("Await Response"). In this response they may either send plans directly to you or ask for further information before being able to do so, particularly if any payments or authorisations are required.
- 2. LSBUD Members who do not have assets registered within your search area. ("Not Affected")
- 3. Non LSBUD Members who may have assets within your search area. Please note that this list is not exhaustive and all details are provided as a guide only. It is your responsibility to identify and consult with all asset owners before proceeding.



Enquiry Confirmation LSBUD Ref: 23470833

Date of enquiry: 05/10/2021 Time of enquiry: 15:21

LSBUD Members who have assets registered on the LSBUD service within the vicinity of your search area.

List of affected LSBUD members			
Asset Owner	Phone/Email	Emergency Only	Status
Scottish and Southern Electricity Networks			Await response
SGN			Await response

LSBUD Members who do not have assets registered on the LSBUD service within the vicinity of your search area. Please be aware that LSBUD Members make regular changes to their assets and this list may vary for new enquiries in the same area.

	List of not affected LSBUD members	
AWE Pipeline	Balfour Beatty Investments Limited	BOC Limited (A Member of the Linde Group)
Box Broadband	BP Exploration Operating Company Limited	BPA
Cadent Gas	Carrington Gas Pipeline	CATS Pipeline c/o Wood Group PSN
Cemex	Centrica Storage Ltd	CNG Services Ltd
Concept Solutions People Ltd	ConocoPhillips (UK) Teesside Operator Ltd	Diamond Transmission Corporation
DIO (MOD Abandoned Pipelines)	DIO (MOD Live Pipelines)	E.ON UK CHP Limited
EirGrid	Electricity North West Limited	ENI & Himor c/o Penspen Ltd
EnQuest NNS Limited	EP Langage Limited	ESP Utilities Group
ESSAR	Esso Petroleum Company Limited	euNetworks Fiber UK Ltd
Exolum Pipeline System	Fulcrum Pipelines Limited	Gamma
Gas Networks Ireland (UK)	Gateshead Energy Company	Gigaclear Ltd
Gtt	Harbour Energy	Heathrow Airport LTD
Humbly Grove Energy	IGas Energy	INEOS FPS Pipelines
INEOS Manufacturing (Scotland and TSEP)	INOVYN ChlorVinyls Limited	INOVYN Enterprises Limited
Intergen (Coryton Energy or Spalding Energy)	Jurassic Fibre Ltd	Last Mile
Mainline Pipelines Limited	Manchester Jetline Limited	Manx Cable Company
Marchwood Power Ltd (Gas Pipeline)	Melbourn Solar Limited	Murphy Utility Assets
National Grid Electricity Transmission	National Grid Gas Transmission	Neos Networks
Northumbrian Water Group	NPower CHP Pipelines	NTT Global Data Centers EMEA UK Ltd
NYnet Ltd	Oikos Storage Limited	Ørsted
Palm Paper Ltd	Perenco UK Limited (Purbeck Southampton Pipeline)	Petroineos
Phillips 66	Portsmouth Water	Premier Transmission Ltd (SNIP)
Redundant Pipelines - LPDA	RWE - Great Yarmouth Pipeline (Bacton to Great Yarmouth Power Station)	RWEnpower (Little Barford and South Haven)
SABIC UK Petrochemicals	Scottish Power Generation	Seabank Power Ltd
SES Water	Shell	Shell NOP
SSE Generation Ltd	SSE Transmission	SSE Utility Solutions Limited
Tata Communications (c/o JSM Construction Ltd)	Total Colnbrook Pipelines	Total Finaline Pipelines
Transmission Capital	UK Power Networks	Uniper UK Ltd

University of Cambridge Granta Backbone
Network

Veolia ES SELCHP Limited

Veolia ES Sheffield Ltd

VPI Power Limited

Wales and West Utilities

West of Duddon Sands Transmission Ltd

Western Power Distribution

Westminster City Council

Zayo Group UK Ltd c/o JSM Group Ltd



Enquiry Confirmation LSBUD Ref: 23470833

Date of enquiry: 05/10/2021 Time of enquiry: 15:21

The following Non-LSBUD Members may have assets in your search area. It is YOUR RESPONSIBILITY to contact them before proceeding. Please be aware this list is not exhaustive and it is your responsibility to identify and contact all asset owners within your search area.

Non-LSBUD members (Asset owners not registered on LSBUD)			
Asset Owner	Preferred contact method	Phone	Status
ВТ			Not Notified
CenturyLink Communications UK Limited			Not Notified
CityFibre			Not Notified
Colt			Not Notified
ENGIE			Not Notified
GTC			Not Notified
Mobile Broadband Network Limited			Not Notified
Sky UK Limited			Not Notified
Sota			Not Notified
Teliasonera			Not Notified
Thames Water			Not Notified
Utility assets Ltd			Not Notified
Verizon Business			Not Notified
Virgin Media			Not Notified
Vodafone			Not Notified
Wokingham District Council (Structures)			Not Notified

Disclaimer

Please refer to LinesearchbeforeUdig's Terms of Use for full terms of use available at www.linesearchbeforeudig.co.uk

The results of this Enquiry are personal to the Enquirer and shall not be shared with or relied upon by any other party. The asset information on which the Enquiry results are based has been provided by LSBUD Members, therefore LinesearchbeforeUdig will provide no guarantee that such information is accurate or reliable nor does it monitor such asset information for accuracy and reliability going forward. There may also be asset owners which do not participate in the enquiry service operated by LinesearchbeforeUdig, including but not exclusively those set out above. Therefore, LinesearchbeforeUdig cannot make any representation or give any guarantee or warranty as to the completeness of the information contained in the enquiry results or accept any responsibility for the accuracy of the mapping images used. LinesearchbeforeUdig and its employees, agents and consultants accept no liability (save that nothing in this Enquiry Confirmation excludes or limits our liability for death or personal injury arising from our negligence, or our fraud or fraudulent misrepresentation, or any other liability that cannot be excluded or limited by English law) arising in respect thereof or in any other way for errors or omissions including responsibility to any person by reason of negligence.