



Inspections In Date Order - Latest First

Road Name: 44701420 - Silverdale Road - Earley, 44701420

Date Due: 29/05/2022 00:00:00

Date Completed: 18/05/2022 10:16:00

Inspector:

Weather: ?

Route: Walked Route 16 (3 Monthly)

Surface Condition: DRY

Defects Found: True

Inspection Method: ?

Date Due: 28/02/2022 00:00:00

Date Completed: 18/02/2022 09:25:00

Inspector:

Weather: ?

Route: Walked Route 16 (3 Monthly)

Surface Condition: DAMP

Defects Found: True

Inspection Method: ?

**Defects In Date Order - Latest First****Road Name:** 44701420 - Silverdale Road - Earley, 44701420**Defect Number :** ?**Source:****Date Raised:** 14/03/2022 15:00:50**Date Completed:** 01/01/9999 00:00:00**Location:** Silverdale Rd, by minor entrance to Loddon School
lat: 51.43450007
lon: -0.91284256**Priority :** N/A**Description:** ?**Defect Number :** D2124780**Source:****Date Raised:** 07/01/2022 09:54:43**Date Completed:** 07/01/2022 12:00:00**Location:** clear surcharging gully including jetting gully outlet. see history W2231657
Location: gully located between junction with Gipsy Lane and number 12
TM may be required. Any problems call Nawaz/Eddie
Notes
Near a junction**Priority :** 24 Hours - Urgent**Description:** ?**Defect Number :** D2125119**Source:****Date Raised:** 24/01/2022 12:10:00**Date Completed:** 25/01/2022 09:13:04**Location:** Opposite 207 in grass verge**Priority :** 24 Hours - Urgent**Description:** Please make safe missing bollard in the grass verge opposite 207
Road Speed: 20MPH
Approx Road Width: 6.0M.
Approx Traffic Flow: med, depending on time of day.
Approx HGV / Bus Traffic Flow: low
Footways: yes
Near Bend: Yes
Near Pedestrian Crossing: Yes
Near Traffic Signals: No
Near Junction: Yes, with allendale road
Near School: No
Near Roundabout: No



Defect Number : D2125800

Source:

Date Raised: 22/02/2022 12:10:22

Date Completed: 22/02/2022 13:45:00

Location: Lamp Column 022 Outside 83 opposite 144 Asset Id:2592

Priority : 2 Hour - Emergency

Description: Emergency call out requested by JB - email came from VH admin - JB called through to AA on 22.02.22 @ 11.45 to request 2-hour attendance.

Report of column outside 83 being struck after accident.

Reported as column hit by vehicle. The column has actually just been scraped. No further damage.- CS

Defect Number : D2125852

Source:

Date Raised: 24/02/2022 08:14:29

Date Completed: 24/02/2022 10:52:05

Location: Please can you follow up with Highways and try to get the car accident on Silverdale Rd glass swept up? I've left a message but no idea if it was received- glass from 81 - 85 Silverdale Rd. Think maybe some traffic calming needs considering too. That's two really bad accidents in as many months on the same stretch!

Priority : 24 Hours - Urgent

Description: Please can you follow up with Highways and try to get the car accident on Silverdale Rd glass swept up? I've left a message but no idea if it was received- glass from 81 - 85 Silverdale Rd. Think maybe some traffic calming needs considering too. That's two really bad accidents in as many months on the same stretch!

Defect Number : D2125883

Source:

Date Raised: 24/02/2022 12:38:00

Date Completed: 25/03/2022 10:45:00

Location: Left hand side of carriageway at sign for Silverdale Youth Community Centre & schools

Priority : 28 Days - Standard Response

Description: S3 L2

Permanent repair required 10mm DBM approx 1sq mtr & please repaint yellow line

Road Speed: 20MPH

Approx Road Width: 6M Approx

Traffic Flow: High, depending on time of day. Approx HGV / Bus Traffic Flow: High

Approx pedestrian volume along High

Footways: Yes

Near Bend: Yes

Near Pedestrian Crossing: No

Near Traffic Signals: No

Near Junction: Yes

Near School: Yes

Near Roundabout: No

Other hazard: Shops & community centre

TM recommended Yes

Defect Number : D2125956

Source:

Date Raised: 28/02/2022 08:59:00

Date Completed: 01/03/2022 09:46:11

Location: As per map

Priority : 3 Days

Description: Mixed waste



Defect Number : D2126195

Source:

Date Raised: 09/03/2022 08:02:00

Date Completed: 10/03/2022 11:45:48

Location: Between number 58 and the junction to Silverdale Road

Priority : 24 Hours - Urgent

Description: Please make safe pothole, marked outside number 58, close to the junction with Silverdale road

Road Speed: 30MPH

Approx Road Width: 6.0M.

Approx Traffic Flow: low, depending on time of day.

Approx HGV / Bus Traffic Flow: low

Footways: yes

Near Bend: Yes

Near Pedestrian Crossing: No

Near Traffic Signals: No

Near Junction: yes

Near School: No

Near Roundabout: No

Defect Number : D2126317

Source: Highway Assets

Date Raised: 14/03/2022 15:01:00

Date Completed: 01/01/9999 00:00:00

Location: ?

Priority : 28 Days - Standard Response

Description: ?

Defect Number : D2126574

Source:

Date Raised: 24/03/2022 08:42:37

Date Completed: 28/03/2022 11:45:00

Location: This afternoon there was litter all over the pavement beside the Turkish Barber (shown as Wikd Beauty on the map) together with an old length of carpet around the base of a tree trunk. There also a lot of litter outside Herbie's Pizza in the same precinct.

Priority : 3 Days

Description: This area is often dirty (although nowhere near as bad as it is today). This is not cleaned twice a week as schedule says or not swept on the 18th of March, please sweep as it looks bad around this area.

Defect Number : D2126641

Source:

Date Raised: 28/03/2022 07:08:00

Date Completed: 28/03/2022 11:05:44

Location: dumped under the tree next to Tesco wall on the corner of Silverdale Road and Silverdale Parade, to the side of the flats and the Turkish barbers .

Priority : 3 Days

Description: dumped under the tree next to Tesco wall on the corner of Silverdale Road and Silverdale Parade, to the side of the flats and the Turkish barbers .



Defect Number : D2228928

Source:

Date Raised: 12/07/2022 08:26:00

Date Completed: 01/01/9999 00:00:00

Location: Outside number 54 opposite junction to Hill side road

Priority : 28 Days - Standard Response

Description: Please lift and reset dropped kerb outside number 54 opposite hillside Road

Road Speed: 30MPH

Approx Road Width: 6.0M.

Approx Traffic Flow: med, depending on time of day.

Approx HGV / Bus Traffic Flow: low

Footways: yes

Near Bend: Yes

Near Pedestrian Crossing: No

Near Traffic Signals: No

Near Junction: yes

Near School: yes

Near Roundabout: No



Enquiries In Date Order - Latest First

Road Name: 44701420 - Silverdale Road - Earley, 44701420

Enquiry Number: W2231657

Assigned CSO: Flooding

Date Raised: 06/01/2022 12:30:00

Date Completed: 01/01/9999 00:00:00

Location: Silver dale Road east end

Description: Gully blocked and overflowing

Recommended Action:

Enquiry Number: W2232213

Assigned CSO: Highway Assets

Date Raised: 23/01/2022 18:42:00

Date Completed: 01/01/9999 00:00:00

Location: Silverdale Rd, Earley, in verge outside No.292

Description: Missing bollard. Bollard is in verge to prevent parking. It has disappeared leaving behind a hole, filled with rubbish

Recommended Action:

Enquiry Number: W2232532

Assigned CSO: Inspection Area 2

Date Raised: 02/02/2022 14:37:00

Date Completed: 03/02/2022 12:25:00

Location: on pavement between number 19 and 21

Description: resident is having building work done on their property and the builders have really made a mess on the pavement with concrete etc. can we knock the resident and get it cleared up.

Recommended Action:

Enquiry Number: W2232912

Assigned CSO: Highway Assets

Date Raised: 13/02/2022 18:57:00

Date Completed: 01/01/9999 00:00:00

Location: Opposite Maiden Erlegh and Aldryngton Schools and the Silverdale shopping precinct.

Description: Could all of the road markings both sides of this busy zebra crossing please be renewed as these are in a poor state of repair.

Recommended Action:

Enquiry Number: W2233094

Assigned CSO: Highway Assets

Date Raised: 18/02/2022 08:27:00

Date Completed: 01/01/9999 00:00:00

Location: Silverdale Road, by Silver Brook Close, approaching Bend at Loddon Primary School.

Description: Please forward to Highways Assets. As part of Highways inspection found lettering worn off at SLOW in cway.

Recommended Action:



Enquiry Number: W2233095

Assigned CSO: Flooding

Date Raised: 18/02/2022 08:30:00

Date Completed: 01/01/9999 00:00:00

Location: Opposite 38 Silverdale Rd

Description: Please forward to Flooding. As part of Highways inspection found gully blocked causing standing water in cway.

Recommended Action:

Enquiry Number: W2233386

Assigned CSO: Highway Assets

Date Raised: 22/02/2022 20:04:00

Date Completed: 01/01/9999 00:00:00

Location: Zebra crossing and road surface either side.

Description: Besides the road markings that need attending to (and reported on 13th February 2022), in December 2019 it was acknowledged by Stefan Sidorowicz that the anti-skid surface eitherside of the pedestrian crossing needed to be replaced. This does not appear to have been done.

Recommended Action:

Enquiry Number: W2233532

Assigned CSO:

Date Raised: 26/02/2022 12:32:00

Date Completed: 01/03/2022 09:46:11

Location: ?

Description: ?

Recommended Action:

Enquiry Number: W2233598

Assigned CSO: Tree Management

Date Raised: 28/02/2022 13:18:00

Date Completed: 30/03/2022 13:48:00

Location: 38 Silverdale Road RG6 7LS

Description: we live opposite Loddon County School where there is a row of very tall conifers. During the recent storms part of one of the trees was broken off, Are you able to confirm that these trees have or will been checked and are not in danger of coming down in the nex storm

Recommended Action:

Enquiry Number: W2234265

Assigned CSO:

Date Raised: 14/03/2022 11:33:00

Date Completed: 01/01/9999 00:00:00

Location: The bin concerned is outside Herbies take away restaurant on Silverdale Road parade of shops

Description: I am reporting a problem with the waste bin along the road from this bin which does not seem to have its own link to report. It is the litter bin outside Herbies on Silverdale Road which either needs to be emptied more regularly please or another additional bin put in its place as it is constantly overflowing with take away wrappings. The is a request from Maiden Erlegh School.
Thank you

Recommended Action:



Enquiry Number: W2234444

Assigned CSO:

Date Raised: 16/03/2022 23:57:00

Date Completed: 17/03/2022 07:03:00

Location: Entrance to flats above shops next to Tesco express car park

Description: Graffiti on wall just by stairwell going up to flats. Cannot be pleasant for people in the housing

Recommended Action:

Enquiry Number: W2234704

Assigned CSO:

Date Raised: 23/03/2022 17:14:00

Date Completed: 01/01/9999 00:00:00

Location: This area is often dirty (although nowhere near as bad as it is today).

Description: This afternoon there was litter all over the pavement beside the Turkish Barber (shown as Wikd Beauty on the map) together with an old length of carpet around the base of a tree trunk. There also a lot of litter outside Herbie's Pizza in the same precinct.

Recommended Action:

Enquiry Number: W2234731

Assigned CSO:

Date Raised: 24/03/2022 11:10:00

Date Completed: 28/03/2022 11:05:44

Location: dumped under the tree next to Tesco wall on the corner of Silverdale Road and Silverdale Parade, to the side of the flats and the Turkish barbers .

Description: Old carpets

Recommended Action:

Enquiry Number: W2235338

Assigned CSO: Street Lighting

Date Raised: 07/04/2022 14:54:00

Date Completed: 08/04/2022 09:15:00

Location: Lamp column no. 030 Silverdale Road, Earley (Outside 121/123 opposite 194) - unique ID 002600.

Description: ?

Recommended Action:

Enquiry Number: W2238857

Assigned CSO: **Date Completed:**

Date Raised: 11/07/2022 11:04:00

01/01/9999 00:00:00

Location: This is located outside 54 Silverdale Road.

Description: A drop kerb slab has come loose. It pivots upwards when driven over and is a trip hazard.

Recommended Action:



Orders In Date Order - Latest First

Road Name: 44701420 - Silverdale Road - Earley, 44701420

Order Number: ORD2200347

Date Raised: 04/03/2022 12:04:25

Location: 44701420 - SILVERDALE ROAD - EARLEY

Description: bin come off brackets, re-fixing needed

Originator:

Date Completed: 24/05/2022 12:49:00

Date Instructed: 19/04/2022 15:58:43

Priority: (46) Days

Order Number: ORD2200657

Date Raised: 07/04/2022 17:15:31

Location: 44701420 - SILVERDALE ROAD - EARLEY

Description: Lamp column no. 030 Silverdale Road, Earley (Outside 121/123 opposite 194) - unique ID 002600.
Check light - resident reported light as out and Telecell ID 0003094597-?? hasn't communicated since 5/4/22.

Originator:

Date Completed: 12/04/2022 08:09:00

Date Instructed: 07/04/2022 17:16:42

Priority: 28 Days

Steel 5m Fabrikat 5M01A(76)P/T with Holophane V-MAXv1 3920lm LED P/T lantern and Telensa Telecell NEMA+In Dim M (0003094597-??).

Order Number: ORD2200698

Date Raised: 12/04/2022 14:01:14

Location: 44701420 - SILVERDALE ROAD - EARLEY

Description: Install new gully(marked with white paint) on Silverdale Road near jct with Gipsy Lane and connect to downstream gully.

- . Road Speed limit: 30MPH
- . Road Width: 5.0M
- . Traffic Flow: High, Medium, Low depending on time of day.
- . HGV / Bus Traffic Flow: Low
- . Footways: yes
- . Footway width: N/A
- . Near Bend: No
- . Near Pedestrian Crossing: Yes
- . Near Traffic Signals: No
- . Near Junction: Yes
- . Near School: No
- . Near Roundabout:
- . Restricted working hours: yes

Other: TM will be required

Originator:

Date Completed: 13/05/2022 12:02:20

Date Instructed: 12/04/2022 14:08:29

Priority: 31 Days

Order Number: ORD2200701

Date Raised: 12/04/2022 14:19:42

Location: 44701420 - SILVERDALE ROAD - EARLEY

Description: Install 3m ACO drain to rear of footway outside 63 Lakeside Earley and connect to new gully at kerb edge then to existing gully outside 58 Lakeside

Originator:

Date Completed: 01/01/9999 00:00:00

Date Instructed: 12/04/2022 14:49:13

Priority: 31 Days