

Defect Report




Defect Reference: D2339294

Source - Rebecca Barnes

Defect Category -	Inspection	Ward -	Hurst
Defect Type -	Carriageway	Contractor -	VolkerHighways
Defect Detail -	Pothole	Required Completion Date -	25/10/2023 13:44:00
Priority -	24 Hours - Urgent	Actual Completion Date -	24/10/2023 13:55:03
Budget -	Highways Reactive	Date Recorded -	24/10/2023 13:44:00

Street -	44700202 - BROADCOMMON ROAD - HURST
Location -	No significant land marks. WhatThreeWords ///digit.bind.intervals
Comments -	<p>Please make safe pothole marked on broadcommom road. No significant land marks. WhatThreeWords ///digit.bind.intervals</p> <p>Note this pothole is filled with water.</p> <p>Permanent repair if possible, but please let me know. RB</p> <p>Road Speed: national speed limit 60MPH Approx Road Width: 5.0M. Approx Traffic Flow: low, depending on time of day. Approx HGV / Bus Traffic Flow: low Footways: no Near Bend: Yes Near Pedestrian Crossing: No Near Traffic Signals: No Near Junction: no Near School: no Near Roundabout: No</p>



Defect Report



Defect Report



Defect Report



Defect Report

No Associated Images

Defect Report



Defect Report

